



报告编号	结论	报告日期	图片
DAJC-7F38670-2021	合格	2021-09-01	
DAJC-7F38671-2021	合格	2021-09-01	
DAJC-7F38672-2021	合格	2021-09-01	
DAJC-7F38673-2021	合格	2021-09-01	

DAJC-7F38674-2021	合格	2021-09-01	
DAJC-7F10389-2021	合格	2021-09-01	 经度: 115.281282 纬度: 42.143386 地址: 内蒙古自治区锡林郭勒盟正镶白旗 天气: 18 ~ 24℃ 西南风 备注: 瑞鑫铁矿
DAJC-7F10390-2021	合格	2021-09-01	 经度: 115.281298 纬度: 42.143571 地址: 内蒙古自治区锡林郭勒盟正镶白旗 天气: 16 ~ 24℃ 西南风 备注: 瑞鑫铁矿
DAJC-7F10391-2021	合格	2021-09-01	 经度: 115.278251 纬度: 42.143303 地址: 内蒙古自治区锡林郭勒盟正镶白旗 天气: 18 ~ 24℃ 西南风 备注: 瑞鑫铁矿

DAJC-7F10392-2021	合格	2021-09-01	 经度: 115.278468 纬度: 42.143430 地址: 内蒙古自治区锡林郭勒盟正镶白旗 天气: 18 ~ 24℃ 西南风 备注: 瑞鑫铁矿
DAJC-7F10411-2021	合格	2021-09-01	 经度: 正在获取中 纬度: 正在获取中 地址: 网络获取失败 天气: 正在获取中
DAJC-7F10457-2021	合格	2021-09-05	 经度: 120.201908 纬度: 49.300818 海拔: 0.0米 天气: 12 ~ 22℃ 东南风 备注: 天宝矿业

DAJC-7F10458-2021	合格	2021-09-05	 经度: 120.201908 纬度: 49.300818 海拔: 0.0米 天气: 🌤️ 12 ~ 22°C 东南风 备注: 天宝矿业
DAJC-7F11381-2021	合格	2021-09-05	
DAJC-7F11382-2021	合格	2021-09-05	 经度: 正在获取中... 纬度: 正在获取中... 地址: 正在获取中... 备注: 长按水印编辑备注

DAJC-7F13574~576-2021	合格	2021-09-05	
DAJC-7F02061-2021	合格	2021-09-05	
DAJC-7F02062-2021	合格	2021-09-05	

DAJC-7F01105-2021	合格	2021-09-06	 经度：正在获取中 纬度：正在获取中 地址：网络获取失败 备注：长按水印编辑备注
DAJC-7F03126-2021	合格	2021-09-06	 经度：正在获取中... 纬度：正在获取中... 地址：正在获取中... 备注：长按水印编辑备注

DAJC-7F10413-2021	合格	2021-09-06	 现场拍照 经度：正在获取中... 纬度：正在获取中... 地址：正在获取中... 备注：长按水印编辑备注
DAJC-7F10414-2021	合格	2021-09-06	 现场拍照 经度：正在获取中... 纬度：正在获取中... 地址：正在获取中... 备注：长按水印编辑备注

DAJC-7F10415-2021	合格	2021-09-06	 经度：正在获取中 纬度：正在获取中 地址：网络获取失败 备注：长按水印编辑备注
DAJC-7F10424-2021	合格	2021-09-06	
DAJC-7F11405-2021	合格	2021-09-06	 经度：113.57 纬度：37.85 地址：山西省平定县娘子关镇上董村
DAJC-7F11378-2021	合格	2021-09-06	

DAJC-7F11379-2021	合格	2021-09-06	
DAJC-7F11380-2021	合格	2021-09-06	
DAJC-7F13577-2021	合格	2021-09-06	
DAJC-7F13578-2021	合格	2021-09-06	


DAJC-7F13579-2021	合格	2021-09-06	
DAJC-7F13580-2021	合格	2021-09-06	
DAJC-7F13581-2021	合格	2021-09-06	


DAJC-7F13582-2021	合格	2021-09-06	
DAJC-7F13583-2021	合格	2021-09-06	



DAJC-7F13591~593-2021	合格	2021-09-06	 经度: 107.660491 纬度: 26.241374 地址: 网络获取失败 天气: 网络获取失败
DAJC-7F04259-2021	合格	2021-09-07	
DAJC-7F13585~587-2021	合格	2021-09-08	


DAJC-7F13588~590-2021	合格	2021-09-08	
DAJC-7F142472~ 2475-2021	合格	2021-09-08	 经度：120.204194 纬度：49.298357 地址：内蒙古自治区呼伦贝尔市陈巴尔虎旗天宝矿业
DAJC-7F16733~749-2021	合格	2021-09-08	 经度：120.204160 纬度：49.298339 地址：内蒙古自治区呼伦贝尔市陈巴尔虎旗陈旗国营特泥河牧场天宝矿业 海拔：0.0米 天气：☀️ 27~34℃ 南风

DAJC-7F17135~136-2021	合格	2021-09-08	 经度: 120.204194 纬度: 49.298357 地址: 内蒙古自治区呼伦贝尔市陈巴尔虎旗天宝矿业 海拔: 0.0米 天气: 🌤️ 27~34℃ 南风
DAJC-7F22392~396-2021	合格	2021-09-08	 经度: 120.204161 纬度: 49.298398 地址: 内蒙古自治区呼伦贝尔市陈巴尔虎旗陈旗国营特泥河牧场天宝矿业 海拔: 0.0米 天气: 🌤️ 27~34℃ 南风
DAJC-7F10425-2021	合格	2021-09-09	 经度: 118.938123 纬度: 41.849355 地址: 内蒙古自治区赤峰市喀喇沁旗一马吐沟 备注: 长按水印编辑备注


DAJC-7F10426-2021	合格	2021-09-09	 经度: 118.938343 纬度: 41.949262 地址: 内蒙古自治区赤峰市喀喇沁旗一马吐沟 备注: 长按水印编辑备注
DAJC-7F10427-2021	合格	2021-09-09	 经度: 118.942343 纬度: 41.937800 地址: 网络获取失败 备注: 长按水印编辑备注

DAJC-7F10428-2021	合格	2021-09-09	 经度：118.938325 纬度：41.949240 地址：内蒙古自治区赤峰市喀喇沁旗一马吐沟 备注：长按水印编辑备注
DAJC-7F10429-2021	合格	2021-09-09	 经度：118.942321 纬度：41.937785 地址：内蒙古自治区赤峰市喀喇沁旗韩家营子 备注：长按水印编辑备注

DAJC-7F10430-2021	合格	2021-09-09	 经度：正在获取中... 纬度：正在获取中... 地址：正在获取中... 备注：长按水印编辑备注
DAJC-7F10431-2021	合格	2021-09-09	 经度：正在获取中... 纬度：正在获取中... 地址：正在获取中... 备注：长按水印编辑备注
DAJC-7F50078-2021	合格	2021-09-09	

DAJC-7F142498~ 2508-2021	合格	2021-09-10	 经度：118.987583 纬度：46.440202 地址：内蒙古自治区锡林郭勒盟东乌珠穆沁旗阿日楚鲁图
DAJC-7F142509~ 2514-2021	合格	2021-09-10	 经度：网络获取失败 纬度：网络获取失败 地址：正在加载中... 海拔：网络获取失败 天气：网络获取失败 备注：长按水印编辑备注

DAJC-7F142515~ 2516-2021	合格	2021-09-10	 经度: 119.016061 纬度: 46.430683 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗满都胡宝拉格镇 海拔: 979.4米 天气: 16 ~ 18℃ 西南风 备注: 长按水印编辑备注
DAJC-7F142517~ 2525-2021	合格	2021-09-10	 经度: 网络获取失败 纬度: 网络获取失败 地址: 请打开手机GPS 海拔: 网络获取失败 天气: 网络获取失败 备注: 长按水印编辑备注

DAJC-7F142527~ 2535-2021	合格	2021-09-10	 经度: 119.007987 纬度: 46.438958 地址: 网络获取失败 海拔: 948.3米 天气: 网络获取失败 备注: 长按水印编辑备注
DAJC-7F142536~ 2541-2021	合格	2021-09-10	 经度: 119.000570 纬度: 46.439318 地址: 内蒙古自治区锡林郭勒盟东乌珠沁旗锡林郭勒盟山金阿尔哈达矿业有限公司 海拔: 0.0米 天气: 11~19℃ 西北风


DAJC-7F142542~ 2544-2021	合格	2021-09-10	 现场拍照 经度: 118.980790 纬度: 46.438669 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗阿日楚鲁图 海拔: 958.8米 天气: 16 ~ 18℃ 西南风 备注: 长按水印编辑备注
DAJC-7F142545~ 2552-2021	合格	2021-09-10	 现场拍照 经度: 119.392614 纬度: 46.492128 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗满都胡宝拉格镇 海拔: 0.0米 天气: 13 ~ 17℃ 西北风 备注: 长按水印编辑备注


DAJC-7F142553~ 2557-2021	合格	2021-09-10	 经度: 119.392614 纬度: 46.492128 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗满都胡宝拉格镇 海拔: 0.0米 天气: ▲ 13 ~ 17℃ 西北风 备注: 长按水印编辑备注
DAJC-7F142558~ 2563-2021	合格	2021-09-10	 经度: 网络获取失败 纬度: 网络获取失败 地址: 正在加载中... 海拔: 网络获取失败 天气: 网络获取失败 备注: 长按水印编辑备注

DAJC-7F142476、2564-2021	合格	2021-09-10	 经度：118.987583 纬度：46.440202 地址：内蒙古自治区锡林郭勒盟东乌珠穆沁旗阿日楚鲁图
DAJC-7F15734-2021	合格	2021-09-10	 经度：118.993923 纬度：46.442004 地址：内蒙古自治区锡林郭勒盟东乌珠穆沁旗阿日楚鲁图

DAJC-7F15735~736-2021	合格	2021-09-10	 经度: 119.001507 纬度: 46.439612 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗锡林郭勒盟山金阿尔哈达矿业有限公司 海拔: 0.0米 天气: 🌤️ 21 ~ 24℃ 西南风 备注: 长按水印编辑备注
DAJC-7F16750~751-2021	合格	2021-09-10	 经度: 正在获取中... 纬度: 正在获取中... 地址: 正在获取中... 时间: 无法获取北京时间 海拔: 正在获取中... 天气: 正在获取中...

DAJC-7F23136-2021	合格	2021-09-10	
DAJC-7F55035~037-2021	合格	2021-09-10	 经度: 118.986840 纬度: 46.440415 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗阿日楚鲁图
DAJC-7F03130-2021	合格	2021-09-10	 经度: 107.656821 纬度: 26.241482 地址: 贵州省黔南布依族苗族自治州都匀市凯都大道 天气: ☀ 32~33℃ 西南风

DAJC-7F03131-2021	合格	2021-09-10	 经度: 107.660894 纬度: 26.241873 地址: 贵州省黔南布依族苗族自治州都匀市凯都大道
DAJC-7F73003-2021	合格	2021-09-11	
DAJC-7F73004-2021	合格	2021-09-11	
DAJC-7F23134-2021	合格	2021-09-13	

DAJC-7F11410-2021	合格	2021-09-13	
DAJC-7F11411-2021	合格	2021-09-13	
DAJC-7F11412-2021	合格	2021-09-13	
DAJC-7F11413-2021	合格	2021-09-13	

DAJC-7F11414-2021	合格	2021-09-13	
DAJC-7F11415-2021	合格	2021-09-13	
DAJC-7F11416-2021	合格	2021-09-13	
DAJC-7F11417-2021	合格	2021-09-13	

DAJC-7F11418-2021	合格	2021-09-13	
DAJC-7F11419-2021	合格	2021-09-13	
DAJC-7F11420-2021	合格	2021-09-13	
DAJC-7F50080-2021	合格	2021-09-13	

DAJC-7F50081-2021	合格	2021-09-13	
DAJC-7F50082-2021	合格	2021-09-13	
DAJC-7F11384-2021	合格	2021-09-14	
DAJC-7F11385-2021	合格	2021-09-14	

DAJC-7F11386-2021	合格	2021-09-14	
DAJC-7F11387-2021	合格	2021-09-14	
DAJC-7F11388-2021	合格	2021-09-14	
DAJC-7F11389-2021	合格	2021-09-14	

DAJC-7F11390-2021	合格	2021-09-14	
DAJC-7F11391-2021	合格	2021-09-14	
DAJC-7F11392-2021	合格	2021-09-14	
DAJC-7F11393-11400-2021	合格	2021-09-14	



DAJC-7F11401-403-2021	合格	2021-09-14	
DAJC-7F38711-2021	合格	2021-09-15	


DAJC-7F38712-2021	合格	2021-09-15	
DAJC-7F38713-2021	合格	2021-09-15	

DAJC-7F38714-2021	合格	2021-09-15	
DAJC-7F38715-2021	合格	2021-09-15	

DAJC-7F38716-2021	合格	2021-09-15	
DAJC-7F38717-2021	合格	2021-09-15	

DAJC-7F11406-2021	合格	2021-09-15	 经度: 118.329084 纬度: 41.730678 地址: 内蒙古自治区赤峰市喀喇沁旗三 地 备注: 长按水印编辑备注
DAJC-7F11407-409-2021	合格	2021-09-15	 经度: 正在获取中... 纬度: 正在获取中... 地址: 网络获取失败 备注: 长按水印编辑备注
DAJC-7F50079-2021	合格	2021-09-16	

DAJC-7F61098-2021	合格	2021-09-16	 海拔：正在获取中... 天气：正在获取中...
DAJC-7F12117-2021	合格	2021-09-20	 经度：网络获取失败 纬度：网络获取失败 地址：正在加载中... 时间：网络获取失败 海拔：网络获取失败 天气：网络获取失败 备注：长按水印编辑备注
DAJC-7F13594~596-2021	合格	2021-09-20	 经度：网络获取失败 纬度：网络获取失败 地址：正在加载中... 时间：网络获取失败 海拔：网络获取失败 天气：网络获取失败 备注：长按水印编辑备注




DAJC-7F13597~598-2021	合格	2021-09-20	
DAJC-7F11421-428-2021	合格	2021-09-21	
DAJC-7F38737-2021	合格	2021-09-22	

DAJC-7F38738-2021	合格	2021-09-22	
DAJC-7F38739-2021	合格	2021-09-22	
DAJC-7F38740-2021	合格	2021-09-22	

DAJC-7F31127-2021	合格	2021-09-22	
DAJC-7F31128-2021	合格	2021-09-22	
DAJC-7F31129-2021	合格	2021-09-22	
DAJC-7F31130-2021	合格	2021-09-22	

DAJC-7F31131-2021	合格	2021-09-22	
DAJC-7F23137-2021	合格	2021-09-26	
DAJC-7F23138-2021	合格	2021-09-26	
DAJC-7F11433-2021	合格	2021-09-28	

DAJC-7F11434-2021	合格	2021-09-28	
DAJC-7F38744-2021	合格	2021-09-30	
DAJC-7F38751-2021	合格	2021-09-30	

DAJC-7F38752-2021	合格	2021-09-30	
DAJC-7F38770-2021	合格	2021-09-30	
DAJC-7F38771-2021	合格	2021-09-30	

DAJC-7F04268-2021	合格	2021-09-30	
DAJC-7F30239-2021	合格	2021-09-30	 经度: 117.584970 纬度: 36.221565 地址: 山东省济南市莱芜区方下河大桥21号嘶马河大桥
DAJC-7F30240-2021	合格	2021-09-30	 经度: 117.584975 纬度: 36.221570 地址: 山东省济南市莱芜区方下河大桥21号嘶马河大桥
DAJC-7F30241-2021	合格	2021-09-30	 经度: 117.584904 纬度: 36.221134 地址: 山东省济南市莱芜区方下河大桥19号嘶马河大桥

DAJC-7F30242-2021	合格	2021-09-30	
DAJC-7F30243-246-2021	合格	2021-09-30	
DAJC-7F50085-2021	合格	2021-09-30	
DAJC-7F142644-2021	合格	2021-10-01	

DAJC-7F15770-2021	合格	2021-10-01	
DAJC-7F61117-2021	合格	2021-10-03	 经度: 117.740520 纬度: 46.019088 海拔: 929.0米 天气: 🌤️ 19 - 22°C 南风

DAJC-7F61118-2021	合格	2021-10-03	 经度: 117.740606 纬度: 46.019096 海拔: 941.1米 天气: 🌤️ 19 ~ 22°C 南风
DAJC-7F61119-2021	合格	2021-10-03	 经度: 117.740520 纬度: 46.019088 海拔: 929.0米 天气: 🌤️ 19 ~ 22°C 南风

DAJC-7F61120-2021	合格	2021-10-03	 经度: 117.740606 纬度: 46.019096 海拔: 941.1米 天气: 🌤️ 19 ~ 22°C 南风
DAJC-A402029-2021	合格	2021-09-05	 经度: 112.456845 纬度: 39.451956 地址: 山西省朔州市平鲁区 陶村村 海拔: 1218.6米 天气: 🌤️ 19 ~ 23°C 西北风
DAJC-7F30223-226-2021	合格	2021-09-05	

DAJC-7F30231-2021	合格	2021-09-05	
DAJC-7F30232-237-2021	合格	2021-09-05	

DAJC-7F31101-110-2021	合格	2021-09-05	
DAJC-7F31111-120-2021	合格	2021-09-05	

DAJC-7F31121-126-2021	合格	2021-09-05	
DAJC-7F32392-2021	合格	2021-09-05	 经度: 119.004833 纬度: 46.433999 地址: 内蒙古自治区锡林郭勒盟东乌珠穆沁旗 锡林郭勒盟山金阿尔哈达矿业有限公司 海拔: 976.9米 天气: ☁️ 25 ~ 25°C 东北风

DAJC-7F32393-2021	合格	2021-09-05	 经度: 119.004970 纬度: 46.433963 地址: 内蒙古自治区锡林郭勒盟东乌珠沁旗 锡林郭勒盟山金阿尔哈达矿业有限公司 海拔: 976.7米 天气: ☀ 25 - 25℃ 东北风
DAJC-7F33070-077-2021	合格	2021-09-05	

DAJC-7F49035-2021	合格	2021-09-05	
DAJC-7F49036-2021	合格	2021-09-05	

DAJC-7F49037-2021	合格	2021-09-05	
DAJC-7F49038-2021	合格	2021-09-05	


DAJC-7F49039-2021	合格	2021-09-05	
DAJC-7F49040-2021	合格	2021-09-05	

DAJC-7F75008-2021	合格	2021-09-05	
DAJC-7F75009-2021	合格	2021-09-05	
DAJC-7F75010-2021	合格	2021-09-05	

DAJC-7F75011-2021	合格	2021-09-05	
DAJC-7F75012-2021	合格	2021-09-05	
DAJC-7F10338-2021	合格	2021-09-05	

DAJC-7F10339-2021	合格	2021-09-05	
DAJC-A402030-2021	合格	2021-09-05	 经度: 112.456945 纬度: 39.451956 地址: 山西省朔州市平鲁区陶村村 海拔: 1218.6米 天气: 19 ~ 23℃ 西北风
DAJC-108168-2021	合格	2021-09-06	 经度: 107.684597 纬度: 26.238307 地址: 贵州省黔南布依族苗族自治州都匀市匀东镇321国道 海拔: 0.0米

DAJC-108169-2021	合格	2021-09-06	 现场拍照 经度: 107.684597 纬度: 26.238307 地址: 贵州省黔南布依族苗族自治州都匀市匀东镇321国道 海拔: 0.0米
DAJC-108170-2021	合格	2021-09-06	 现场拍照 经度: 107.661101 纬度: 26.242035 地址: 贵州省黔南布依族苗族自治州都匀市凯都大道 天气: 32 ~ 33℃ 西南风
DAJC-108171-2021	合格	2021-09-06	 现场拍照 经度: 107.661101 纬度: 26.242035 地址: 贵州省黔南布依族苗族自治州都匀市凯都大道 天气: 32 ~ 33℃ 西南风

DAJC-108172-2021	合格	2021-08-16	 经纬: 30°17'33.118" 北纬: 25°55'2.68" 地址: 贵州省毕节市赫章县翰街彝族苗族乡 海拔: 1094
DAJC-128109-2021	合格	2021-09-06	 海拔: 正在获取中... 天气: 正在获取中...
DAJC-128110-2021	合格	2021-09-06	 海拔: 正在获取中... 天气: 正在获取中...

DAJC-128111-2021	合格	2021-09-06	 海拔：正在获取中... 天气：正在获取中...
DAJC-128112-2021	合格	2021-09-06	 海拔：正在获取中... 天气：正在获取中...
DAJC-128117-2021	合格	2021-09-05	 海拔：正在获取中... 天气：正在获取中...

DAJC-128118-2021	合格	2021-09-05	
DAJC-128119-2021	合格	2021-09-05	